



Error code table

Vehicle	BMW / 523 i / 09/1995 - 09/2000 / Saloon
Country of manufacture	D
Cubic capacity/Power	2.5 / 125 kW
Motor tag	25 6 S3/S4
RB key	BMW 378
Sector	All
System	Traction control system / ABS/ASR 5.7

Code	Error	Error type
4	Wheel-speed sensor rear left	incorrect/no signal
5	Wheel-speed sensor rear right	incorrect/no signal
6	Wheel-speed sensor front right	incorrect/no signal
7	Wheel-speed sensor front left	incorrect/no signal
14	Valve relay	faulty
15	Pump motor/engine relay	faulty
21	Control unit ABS/ASC component	faulty
23	Auto stability control variant cod	faulty
24	Ring gear	wrong number of teeth
25	Brake switch	open circuit
30	Wheel-speed sensor rear left	open circuit
31	Wheel-speed sensor rear right	open circuit
32	Wheel-speed sensor front right	open circuit
33	Wheel-speed sensor front left	open circuit
34	ASC pilot valve	faulty
47	Rear left outlet valve	faulty
48	Rear right outlet valve	faulty
49	Front right outlet valve	faulty
50	Front left outlet valve	faulty
51	Rear left inlet valve	faulty
52	Rear right inlet valve	faulty
53	Front right inlet valve	faulty
54	Front left inlet valve	faulty
55	ASC suction valve	faulty

Error code table

12/3/2005

2:47:15 AM

56	CAN data bus	No initialization
58	CAN message, transm. control unit	no communication
59	CAN message, engine control unit	Signal error, Motronic 1
63	Speed comparison	faulty
64	Continuous regulation/interference	faulty
66	Power supply for active sp. sensor	not in range
67	Sporadic interference	occurred
68	ASC shutoff	occurred
75	CAN message, engine control unit	Engine rpm not plausible
76	CAN message, engine control unit	no communication
93	CAN message, engine control unit	Pedal angle not plausible
94	CAN message, engine control unit	Error stored
111	ASC acknowledgement	faulty
112	CAN message, combined instruments	faulty