



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Heating / AC system / Automatic air conditioning 1.0

Code	Error	Error type
00h	Servomotor for ventilation flaps	open circuit
00h	Servomotor for ventilation flaps	short to earth
00h	Servomotor for ventilation flaps	short to B+
00h	Servomotor for ventilation flaps	not plausible
01h	Servomotor for defroster flaps	open circuit
01h	Servomotor for defroster flaps	short to earth
01h	Servomotor for defroster flaps	short to B+
01h	Servomotor for defroster flaps	not plausible
02h	Control motor: footwell flap (FW)	open circuit
02h	Control motor: footwell flap (FW)	short to earth
02h	Control motor: footwell flap (FW)	short to B+
02h	Control motor: footwell flap (FW)	not plausible
03h	Recirc.-air flap servomotor, left	open circuit
03h	Recirc.-air flap servomotor, left	short to earth
03h	Recirc.-air flap servomotor, left	short to B+
03h	Recirc.-air flap servomotor, left	not plausible
04h	Recirc.-air flap servomotor, right	open circuit
04h	Recirc.-air flap servomotor, right	short to earth
04h	Recirc.-air flap servomotor, right	short to B+
04h	Recirc.-air flap servomotor, right	not plausible
06h	Power supply, pollutant/ refrigerant pressure sensor	open circuit
06h	Power supply, pollutant/ refrigerant pressure sensor	short to earth
06h	Power supply, pollutant/ refrigerant	short to B+

Error code table

12/3/2005
3:08:13 AM

06h	Power supply, pollutant/ refrigerant pressure sensor	not plausible
0Bh	Vaporization system temp. sensor	open circuit
0Bh	Vaporization system temp. sensor	short to earth
0Bh	Vaporization system temp. sensor	short to B+
0Bh	Vaporization system temp. sensor	not plausible
0Dh	Heat-exchanger temperature sensor	open circuit
0Dh	Heat-exchanger temperature sensor	short to earth
0Dh	Heat-exchanger temperature sensor	short to B+
0Dh	Heat-exchanger temperature sensor	not plausible
1ah	Fan for passenger-compartment temperature sensor	open circuit
1ah	Fan for passenger-compartment temperature sensor	short to earth
1ah	Fan for passenger-compartment temperature sensor	short to B+
1ah	Fan for passenger-compartment temperature sensor	not plausible
1ch	Pollutants sensor	open circuit
1ch	Pollutants sensor	short to earth
1ch	Pollutants sensor	short to B+
1ch	Pollutants sensor	not plausible
1dh	Refrigerant pressure sensor	open circuit
1dh	Refrigerant pressure sensor	short to earth
1dh	Refrigerant pressure sensor	short to B+
1dh	Refrigerant pressure sensor	not plausible
1eh	Automatic recirc.-air control, heating	open circuit
1eh	Automatic recirc.-air control, heating	short to earth
1eh	Automatic recirc.-air control, heating	short to B+
1eh	Automatic recirc.-air control, heating	not plausible
12h	Interior temperatur sensor	open circuit
12h	Interior temperatur sensor	short to earth
12h	Interior temperatur sensor	short to B+
12h	Interior temperatur sensor	not plausible
15h	Relay for rear-window heater	open circuit
15h	Relay for rear-window heater	short to earth

Error code table

12/3/2005

3:08:13 AM

15h	Relay for rear-window heater	short to B+
15h	Relay for rear-window heater	not plausible
16h	Heating-water pump	open circuit
16h	Heating-water pump	short to earth
16h	Heating-water pump	short to B+
16h	Heating-water pump	not plausible
18h	Heating-water timing valve	open circuit
18h	Heating-water timing valve	short to earth
18h	Heating-water timing valve	short to B+
18h	Heating-water timing valve	not plausible
19h	Fan control voltage	open circuit
19h	Fan control voltage	short to earth
19h	Fan control voltage	short to B+
19h	Fan control voltage	not plausible
21h	Sun sensor	open circuit
21h	Sun sensor	short to earth
21h	Sun sensor	short to B+
21h	Sun sensor	not plausible