



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Instrumentation / Combination instrument 1.0

Code	Error	Error type
01	Sensor voltage supply	faulty
02	Sensor current	Out of operating range
03	Driving operation	signal faulty
04	Trimming operation	signal faulty
05	Steering wheel angle sensor	faulty
06	Steering wheel angle sensor	faulty
07	Steering wheel angle sensor	faulty
08	Steering wheel angle sensor	faulty
09	Steering wheel angle sensor	Intermittent fault
0A	CAN data bus	Wrong software version
0B	Steering wheel angle sensor	No initialization
0C	CAN data bus	faulty
0D	Steering speed	not plausible
0E	Steering wheel angle	not plausible
0F	Steering wheel angle sensor	faulty