



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Lighting / Light switch centre 1.0

Code	Error	Error type
3a	Lamp for high-beam headlight, right	faulty
3b	Lamp for left-inside taillight	faulty
3c	Lamps for licence-plate light	faulty
3d	Lamp for right-inside taillight	faulty
3e	Bulb for rear left fog light	faulty
3f	Lamp for blinker, left rear	faulty
33	Lamp for parking lights, right front	faulty
34	Lamp for left brake/taillight	faulty
35	Lamp for right brake/taillight	faulty
36	Lamp for blinker, right front	faulty
37	Lamp for blinker, left front	faulty
38	Lamp for parking lights, left front	faulty
39	Lamp for high-beam headlight, left	faulty
40	Lamp for blinker, right rear	faulty
41	Lamp for low-beam headlight, right	faulty
42	Lamp for low-beam headlight, left	faulty