



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Anti-theft safeguard / Immobilizer (WFS) 1.0

Code	Error	Error type
00	Key 1	Identification faulty
01	Key 1	Password wrong
02	Key 1	Switch code is defective
0E	Control unit	faulty
10	Key 2	Identification faulty
11	Key 2	Password wrong
12	Key 2	Switch code is defective
1E	Control unit	faulty
1F	Control unit	faulty
20	Key 3	Identification faulty
21	Key 3	Password wrong
22	Key 3	Switch code is defective
2F	Control unit	faulty
30	Key 4	Identification faulty
31	Key 4	Password wrong
32	Key 4	Switch code is defective
3F	Control unit	faulty
40	Key 5	Identification faulty
41	Key 5	Password wrong
42	Key 5	Switch code is defective
50	Key 6	Identification faulty
51	Key 6	Password wrong
52	Key 6	Switch code is defective
60	Key 7	Identification faulty

Error code table

12/3/2005

3:12:21 AM

61	Key 7	Password wrong
62	Key 7	Switch code is defective
70	Key 8	Identification faulty
71	Key 8	Password wrong
72	Key 8	Switch code is defective
7F	Control unit	faulty
80	Key 9	Identification faulty
81	Key 9	Password wrong
82	Key 9	Switch code is defective
90	Key 10	Identification faulty
91	Key 10	Password wrong
92	Key 10	Switch code is defective