



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Comfort electronics / Sun roof operating unit 1.0

Code	Error	Error type
01	Sunroof relay	faulty
02	Hall sensor, sunroof motor	faulty
03	Switch for sunroof	faulty
04	Control unit	faulty