



Error code table

Vehicle	BMW / 325 xi / 09/2000 - / Saloon, All-wheel
Country of manufacture	D
Cubic capacity/Power	2.5 / 141 kW
Motor tag	25 6 S5
RB key	BMW 534
Sector	All
System	Comfort electronics / Key pad for lower center console (UBF) 1.0

Code	Error	Error type
0a	Motor for rear-window blinds	
0b	Motor for rear-window blinds	
01	Terminal 30	
02	Heated seat, left front	
03	Heated seat, right front	
04	Driver seat temperature sensor	
05	Driver seat temperature sensor	
06	Temperature sensor for passenger seat	
07	Temperature sensor for passenger seat	
08	Heated seat, left front	
09	Heated seat, right front	