



## Error code table

|                        |                                                      |
|------------------------|------------------------------------------------------|
| Vehicle                | BMW / 525 ix / 09/1991 - 12/1995 / Saloon, All-wheel |
| Country of manufacture | D                                                    |
| Cubic capacity/Power   | 2.5 / 141 kW                                         |
| Motor tag              | 25 6 S1/S2                                           |
| RB key                 | BMW 297                                              |
| Sector                 | All                                                  |
| System                 | Traction control system / ABS/ABD 5                  |

| Code | Error                          | Error type            |
|------|--------------------------------|-----------------------|
| 2    | Engine control unit            | faulty                |
| 3    | Ignition angle intervention    | faulty                |
| 4    | Wheel-speed sensor rear left   | incorrect/no signal   |
| 5    | Wheel-speed sensor rear right  | incorrect/no signal   |
| 6    | Wheel-speed sensor front right | incorrect/no signal   |
| 7    | Wheel-speed sensor front left  | incorrect/no signal   |
| 14   | Valve relay                    | faulty                |
| 15   | Pump motor/engine relay        | faulty                |
| 21   | Electronic control unit        | faulty                |
| 22   | TD signal                      | faulty                |
| 24   | Ring gear                      | wrong number of teeth |
| 25   | Brake light switch             | open circuit          |
| 27   | LDA response                   | faulty                |
| 29   | Clutch switch                  | open circuit          |
| 30   | Wheel-speed sensor rear left   | open circuit          |
| 31   | Wheel-speed sensor rear right  | open circuit          |
| 32   | Wheel-speed sensor front right | open circuit          |
| 33   | Wheel-speed sensor front left  | open circuit          |
| 34   | ASC pilot valve                | faulty                |
| 36   | Ignition not displ             | faulty                |
| 47   | Rear left outlet valve         | faulty                |
| 48   | Rear right outlet valve        | faulty                |
| 49   | Front right outlet valve       | faulty                |
| 50   | Front left outlet valve        | faulty                |

## Error code table

12/3/2005

2:34:49 AM

|    |                                                         |          |
|----|---------------------------------------------------------|----------|
| 51 | Rear left inlet valve                                   | faulty   |
| 52 | Rear right inlet valve                                  | faulty   |
| 53 | Front right inlet valve                                 | faulty   |
| 54 | Front left inlet valve                                  | faulty   |
| 55 | ASC suction valve                                       | faulty   |
| 60 | Power supply for temperature after-running not in range |          |
| 61 | Central block                                           | faulty   |
| 62 | Brake overheating                                       | occurred |
| 63 | Speed comparison                                        | faulty   |
| 64 | Continuous regulation/interference                      | faulty   |
| 65 | EMS reply                                               | faulty   |